

CROSS REFERENCE REPLACEMENT CHART

DRIVESAVER	ISOFLEX	VARIATION	POLYFLEX
303	no direct replacement		303
353	no direct replacement		no direct replacement
354	no direct replacement		no direct replacement
404	no direct replacement		no direct replacement
404A	IFC4300		434
404AC	IFC4300 special spigot		434P
404V	IFC4600		464
404S	no direct replacement		454
424Y	IFC4200		424
4756	IFC6000 usually fits	Iso larger OD fits zf220a	546
4756PR	IFC6000HT usually fits	Iso larger OD fits zf220a	546
454	no direct replacement		no direct replacement
504	IFC4500		524
504A	no direct replacement		no direct replacement
504AC	no direct replacement		514
504PR	IFC4500HT		no direct replacement
504H	IFC4550		524IRM
504HPR	IFC4550HT		no direct replacement
524Y	IFC4400		534
no direct replacement	IFC4700		547
no direct replacement	IFC4800		484
no direct replacement	IFC4900		1550
554	no direct replacement		no direct replacement
4756	IFC6000	Iso larger OD fits zf220a	546
5756	IFC6100		616_1/2B
5756A	IFC6125	Female spigot	616_1/2A
5756APR	IFC6125HT		616 1/2A
5756AZF	IFC6100	Male Spigot	616 1/2B
5756AZFPR	IFC6100HT		616 1/2B
5756T	IFC6150	Iso 16mm bolts	616 5/8
6256	no direct replacement		636
7256	IFC6300		7206_5/8
7256PR	IFC6300HT		
7258ZPR	no direct replacement		no direct replacement
7306Z	IFC6400		7606
8078Z	no direct replacement		no direct replacement
8010Z	IFC10325	Iso 7mm thicker	
8858Z	no direct replacement		no direct replacement
908 and 908PR	IFC8100	Iso 1/2" thicker	9858_5/8
908S	IFC8200	Iso 1/2" thicker	9114
908AC	no direct replacement		no direct replacement
no direct replacement	IFC8300		7608
no direct replacement	IFC8400		9934
1058	IFC8534		10834
no direct replacement	IFC8500	M20 Bolts used	no direct replacement
no direct replacement	IFC8600		2308
1108	IFC8695		11834
1108A	IFC8690		11834A
1308	no direct replacement		no direct replacement
no direct replacement	IFC8700		2808
no direct replacement	IFC8800		3408